



ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone		Ward No.		Ward Name			
YELAHANKA		5		Jakkuru			
Street ID		Street Name		Significant Landmark			
W0233, W0124, W0239, W0122, W0229, W0020, W0019, W		NA		surrounding area (Babanagar) of kagilu layout			
Segment No.		Total Length (m)					
5/S-W0233/S025019		975.21					
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	161.25	77.620913	13.119077	77.620808	13.117623	W0122	W0193
2	107.43	77.621176	13.118367	77.621086	13.117400	W0124	W0233
3	94.77	77.621468	13.118340	77.621378	13.117488	W0124	DEAD END
4	611.76	77.620156	13.121653	77.619090	13.126330	RI-A18	W0015
Work Details							
History of Road / Lane / Circles							
Name of the Work		Sanctioned Estimated Amount (Rs.)		Sanctioned Year			
Improvements to Roads & Drains at surrounding area (Babanagar) of kagilu layout in ward no 05 Byatarayanapura Sub-Division Yelahanka zone		4000000		2015			
Year	Type of Work		Other Work Type				
2015 - 2016	Asphalting						
Tender	Work Details		Job No. / Work Code				
Tender	Improvements to Roads & Drains at surrounding area (Babanagar) of kagilu layout in ward no 05 Byatarayanapura Sub-Division Yelahanka zone		005-16-000016				
Work Order No.	Work Order Date		Period of Extention				
BBMP/EE/BTP/WO/55/2016-17	16/06/2016		90 DAYS				
Defect Liability Period From	Defect Liability Period To		Multiple road involved with the same Job No/ Work Code #				
16/06/2016	15/06/2017		Yes				
Contractor Details							
Name of Contractor		Contractor Reg No (BBMP/PWD)		Expenditure Booked \ Released (Rs)			
SAMBASHIVA				0.00			

Zone: YELAHANKA

Ward No: 5

Ward Name: Jakkuru

Street ID: W0233,
W0124,
W0239,
W0122,
W0019, W

Phone No.

E-Mail ID

9035637741

Field Inspection Details

Number of Trees

12

Any Other Information

Name

CHANDRAKANTH

Date of Inspection

26/07/2016

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Drain Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Zone: YELAHANKA

Ward No: 5

Ward Name: Jakkuru

Street ID: W0233,
W0124,
W0239,
W0122,
W0233, W

Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARIAH	06/08/2016	25/08/2016	COMPLETED

Zone: YELAHANKA

Ward No: 5

Ward Name: Jakkuru

Street ID: W0233,
W0124,
W0239,
W0122,
W0233, W